




1

**American Institute of Architects (AIA)
Continuing Professional Education**

Credit(s) earned on completion of this course will be reported to AIA CES for AIA members upon completion. Certificates of Completion for both AIA members and non-AIA members are available upon request.

This course is registered with AIA CES for continuing professional education. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product.

Questions related to specific materials, methods, and services will be addressed at the conclusion of this presentation.



2

Course Description

This session will discuss structural failures observed during storm damage assessments and the behavior of wood structures during high wind events. An overview of how high wind forces work, the importance of a complete load path, and how good design and construction practices can improve the storm resistance of buildings will be provided. Both code requirements and APA's above-code recommendations which contribute to improved overall performance in the structural shell will be discussed. They focus on good connection details and common failure modes seen in storm damage assessments and help builders cost effectively build a safer home. By understanding key code requirements and lateral load concepts, home damage in future storms can be minimized.



3


Learning Objectives

1. Recognize the fundamental behavior of wood structures
2. Identify common failure modes.
3. Discusses preventive methods that can reduce damage.
4. Understand the importance of a complete load path.

APA


4

APA Publications



5

APA Publications



6

Publications from Others



7

May 2003 Midwest Tornadoes



8

April 2011 Tornadoes of the South



9

December 2015
Texas Tornado



10

March 2017
Texas Straight Line Winds



11

June 2017
Nebraska Tornado



12



13



14

Enhanced Fujita Scale

EF-Scale	Tornado description	Wind Speed (3-sec gust)	Description of Expected Damage
EF-0	Gale tornado	65-85	Minor or no damage. Peels surface off some roofs; some damage to gutters or siding; branches broken off trees; shallow-rooted trees pushed over.
EF-1	Moderate tornado	86-110	Moderate damage. Roofs severely stripped; mobile homes overturned or badly damaged; loss of exterior doors; windows and other glass broken.
EF-2	Significant tornado	111-135	Considerable damage. <u>Roofs torn off well-constructed houses</u> ; foundations of frame homes shifted; mobile homes completely destroyed; <u>large trees snapped or uprooted</u> ; light-object missiles generated; cars lifted off ground.
EF-3	Severe tornado	136-165	Severe damage. Entire stories of well-constructed houses destroyed; trains overturned; trees debarked; heavy cars lifted off the ground and thrown.
EF-4	Devastating tornado	166-200	Extreme damage. Well-constructed and whole frame houses completely leveled; cars and other large objects thrown and small missiles generated.
EF-5	Incredible tornado	>200	Total Destruction. Strong framed, well built houses leveled off foundations and swept away;

15

Tornado Facts

- 96% of all tornadoes are EF2 and below
- Damaging winds outside vortex are slower than max.
- Unrealistic to protect against EF4, EF5, and some EF3.
- The Enhanced F-scale still is a set of wind estimates (not measurements) based on damage. Tornado loads – more unknown than seismic!
- Safe rooms are NOT a universal remedy
 - There is often little warning to those who are in the tornado path
 - Need recommendations to protect building shell

16

Damage Indicators

- Group of objects that can be used to evaluate a tornado severity
- EF scale currently has 28 damage indicators (DI) or types of structures and vegetation, each with varying number of degrees of damage (DoD)
- The larger the degree of damage, the higher the wind speed and corresponding tornado ratings
- Primary Damage Indicators used in the this report
 - One- or Two-family residences
 - Hardwood Trees



17

Damage Indicator-2 (FR12)

One- And Two-Family Residences (FR12) (1000 – 5000 sq. ft.)

- Typical Construction
 - Roof coverings
 - Roof sheathing and framing
 - Roof geometry
 - Wall claddings
 - Wall sheathing and framing
 - Wall geometry and openings, including attached garages



18

Damage Indicator – 2 (FR12)

DOD	Damage Description	EXP	LB	UB
1	Threshold of visible damage	65	53	80
2	Loss of roof covering material (<20%), gutters and/or awning; loss of vinyl or metal siding	79	63	97
3	Broken glass in doors and windows	96	79	114
4	Uplift of roof deck and loss of significant roof covering material (>20%); collapse of chimney; garage doors collapse inward; failure of porch of carport	97	81	116
5	Entire house shifts off foundation	121	103	141
6	Large sections of roof structure removed; most walls remain standing	122	104	142
7	Exterior walls collapsed	132	113	153
8	Most walls collapsed, except small interior rooms	152	127	178
9	All walls	170	142	198
10	Destruction of engineered and/or well constructed residence; slab swept clean	200	165	220

DOD = Degree of Damage
 EXP = Expected Wind Speed
 LB = Lower Bound Wind Speed
 UB = Upper Bound Wind Speed

19

Damage Indicator – 27 (TH)

27. Trees: Hardwood

Typical Construction

Hardwood: Oak, Maple, Birch, Ash

DOD	Damage Description	EXP	LB	UB
1	Small limbs broken (up to 1" diameter)	60	48	72
2	Large branches broken (1"-3" diameter)	74	61	88
3	Trees uprooted	91	76	118
4	Trunks snapped	110	93	134
5	Trees debarked with only stubs of largest branches remaining	143	123	134

DOD = Degree of Damage
 EXP = Expected Wind Speed
 LB = Lower Bound Wind Speed
 UB = Upper Bound Wind Speed

20

EF-3 Severe damage. Entire stories of well-constructed houses destroyed; trains overturned; trees debarked; heavy cars lifted off the ground and thrown.

Texas Tornado – December 2015



21

**EF-1 Moderate damage. Roofs severely stripped;
mobile homes overturned or badly damaged;
loss of exterior doors; windows and other glass broken.**

Texas Tornado – December 2015



22

Damage Indicators

Texas Tornado – December 2015



23


Nebraska Tornado – June 2017




24



25



26



27

Percentage of Occurrence


EF-Scale	Wind Speed (3-sec gust)	Relative Frequency	Cumulative Percentage	Examples of Damage
EF-0	65-85	53.5 %	53.5 %	
EF-1	86-110	31.6 %	85.1	
EF-2	111-135	10.7 %	95.8	
EF-3	136-165	3.4 %	99.2	
EF-4	166-200	0.7 %	99.9	
EF-5	>200	< 0.1	100	

28


Load Path

IBC 2018 1604.4

"Any system or method of construction to be used shall be based on a rational analysis in accordance with well established principles of mechanics. Such analysis shall result in a system that provides a complete load path capable of transferring loads from their point of origin to the load-resisting elements."



Vertical Load Path




Lateral Load Path

APA

29

Load Path

Vertical (Gravity) Load Path Issues



APA


30

Load Path Continuity



31


Load Path



32

Load Path

Lateral (Sideways) Load Path Issues



33

Lateral Forces

Effects of Forces

Racking




Resisted by Bracing

Base Shear



Resisted by Anchors

Overturning



Resisted by hold-downs
& Dead Load

APA

34

Building for High Wind Resistance



APA

35

Roof Sheathing Connection



- A** Nail roof sheathing with 8d ring shank or screw shank (0.131" x 2-1/2") nails at 4 inches on center along the ends of the sheathing and at gable-end walls, and 6 inches on center along intermediate framing.
- B** Tie gable-end walls back to the structure. One of the weakest links in residential structures during high wind events is the connection between the gable end and the wall below.
- C** Sheath gable-end walls with wood structural panels, such as plywood or oriented strand board (OSB). In past tornado events, gable-end wall failures were frequently observed when non-structural sheathing was used.
- D** For the roof framing to wall connection, use a hurricane/seismic framing anchor or eq connector, attached on the exterior (shear side) of the exterior walls. The roof-to-wall connection should be made on the exterior side of the wall.

36

Roof Sheathing Connection

Texas Tornado – December 2015



37

Texas Tornado – December 2015



38

Tornadoes of the South – 2011




39



40



41



42

Fastener Recommendations

**8d (0.131" x 2-1/2") screw
or ring shank nails**

Enhanced pullout is achieved with ring or spiral shanks nails for enhanced uplift resistance



43

Gable Ends



- A** Nail roof sheathing with 8d ring shank or screw shank (0.131" x 2-1/2") nails at 4 inches on center along the ends of the sheathing and at gable-end walls, and 6 inches on center along intermediate framing.
- B** Tie gable-end walls back to the structure. One of the weakest links in residential structures during high wind events is the connection between the gable end and the wall below.
- C** Sheath gable-end walls with wood structural panels, such as plywood or oriented strand board (OSB). In past tornado events, gable-end wall failures were frequently observed when non-structural sheathing was used.
- D** For the roof framing to wall connection, use a hurricane/seismic framing anchor or equivalent connector, attached on the exterior (sheathing side) of the exterior walls. The roof-to-wall

44

Fayetteville, North Carolina – 2011 Tornadoes



45



46



47




48



49




50



51



52



53




54




Maryland Tornado – July 2017

55



56




57



58



59



60




61




62



63



64




65



66

Roof to Wall Connection

Roof framing to wall connection with hurricane/seismic framing anchor or equivalent connector attached on sheathing side of the exterior walls



67

Connections between floors



68

Texas Tornado – December 2015



69



70



71



72

Rim Board Connections

Garland, Texas – 2015



73

Maryland Tornado – July 2017



74

Rim Board Connections



75

[illegible]

lateral and uplift load continuity is to attach adjacent wall sheathing panels to one another over common framing.

F Nail wall sheathing with 8d common (0.131" x 2-1/2") nails at 4 inches on center at end and edges of wood structural panels and 6 inches on center along intermediate framing. This enhanced nailing will improve the resistance of the wall sheathing panels to negative wind pressure. Staples offer less resistance to blow-off than nails and so a greater number of them are required to achieve the same level of resistance.

G Continuously sheath all walls with wood structural panels including areas around openings for windows and doors.

H Extend wood structural panel sheathing to lap the sill plate. The connection of the wall sheathing panel to the sill plate is important because this is where uplift forces are transferred into the sill plate and into the foundation through the anchor bolts.

I Space 1/2" anchor bolts 32 inches to 48 inches on center with 0.229" x 3" x 3" square plates.



79




80




81



82



83



84

Wall Sheathing

Garland, Texas – 2015



85

Wall Sheathing

Texas Straight Line Wind – March 2017



86


Wall Sheathing

Garland, Texas – 2015




87

Portal Frames



88

Portal Frame



89

Wall Sheathing

Garland, Texas – 2015



90

Wall Sheathing

Garland, Texas – 2016



91

Nebraska Tornado – June 2017



92

Wall Sheathing

Garland, Texas – 2015



93

Veneer Failures

Garland, Texas – 2015



94

Veneer Failures

Garland, Texas – 2015



95

Wall Sheathing

Texas Straight Line Wind - 2017



96

Wall Sheathing Attachment

Nail wall sheathing with 8d common (0.131" x 2-1/2") nails at 4" on center in the boundary of wood structural panel wall sheathing and 6" on center in the intermediate studs

8d Common nails at 6" on center at intermediate supports

8d Common nails at 4" on center at panel ends and edges

APA

97

Wall Sheathing Attachment

APA

Nail-Base Sheathing for Siding and Trim Attachment

CONSTRUCTION GUIDE

TABLE 1-1: REQUIRED NAILING FOR WALL SHEATHING ATTACHMENT TO WOOD STRUCTURAL PANELS (REQUIRED UNLESS OTHERWISE NOTED)		TABLE 1-2: REQUIRED NAILING FOR WALL SHEATHING ATTACHMENT TO WOOD STRUCTURAL PANELS (REQUIRED UNLESS OTHERWISE NOTED)			
Nail Size	Nail Spacing	15-Minimum Edge		15-Minimum Edge	
		Ends and Edges	Intermediate	Ends and Edges	Intermediate
8d	4"	15"	12"	15"	12"
8d	6"	15"	12"	15"	12"
8d	8"	15"	12"	15"	12"
8d	10"	15"	12"	15"	12"
8d	12"	15"	12"	15"	12"
8d	14"	15"	12"	15"	12"
8d	16"	15"	12"	15"	12"
8d	18"	15"	12"	15"	12"
8d	20"	15"	12"	15"	12"
8d	22"	15"	12"	15"	12"
8d	24"	15"	12"	15"	12"
8d	26"	15"	12"	15"	12"
8d	28"	15"	12"	15"	12"
8d	30"	15"	12"	15"	12"
8d	32"	15"	12"	15"	12"
8d	34"	15"	12"	15"	12"
8d	36"	15"	12"	15"	12"
8d	38"	15"	12"	15"	12"
8d	40"	15"	12"	15"	12"
8d	42"	15"	12"	15"	12"
8d	44"	15"	12"	15"	12"
8d	46"	15"	12"	15"	12"
8d	48"	15"	12"	15"	12"
8d	50"	15"	12"	15"	12"
8d	52"	15"	12"	15"	12"
8d	54"	15"	12"	15"	12"
8d	56"	15"	12"	15"	12"
8d	58"	15"	12"	15"	12"
8d	60"	15"	12"	15"	12"
8d	62"	15"	12"	15"	12"
8d	64"	15"	12"	15"	12"
8d	66"	15"	12"	15"	12"
8d	68"	15"	12"	15"	12"
8d	70"	15"	12"	15"	12"
8d	72"	15"	12"	15"	12"
8d	74"	15"	12"	15"	12"
8d	76"	15"	12"	15"	12"
8d	78"	15"	12"	15"	12"
8d	80"	15"	12"	15"	12"
8d	82"	15"	12"	15"	12"
8d	84"	15"	12"	15"	12"
8d	86"	15"	12"	15"	12"
8d	88"	15"	12"	15"	12"
8d	90"	15"	12"	15"	12"
8d	92"	15"	12"	15"	12"
8d	94"	15"	12"	15"	12"
8d	96"	15"	12"	15"	12"
8d	98"	15"	12"	15"	12"
8d	100"	15"	12"	15"	12"

98

Sill Plates and Anchor Bolts

lateral and uplift load continuity is to attach adjacent wall sheathing panels to one another over common framing.


F Nail wall sheathing with 8d common (0.131" x 2-1/2") nails at 4 inches on center at end and edges of wood structural panels and 6 inches on center along intermediate framing. This enhanced nailing will improve the resistance of the wall sheathing panels to negative wind pressure. Staples offer less resistance to blow-off than nails and so a greater number of them are required to achieve the same level of resistance.

G Continuously sheath all walls with wood structural panels including areas around openings for windows and doors.

H Extend wood structural panel sheathing to lap the sill plate. The connection of the wall sheathing panel to the sill plate is important because this is where uplift forces are transferred into the sill plate and into the foundation through the anchor bolts.

I Space 1/2" anchor bolts 32 inches to 48 inches on center with 0.229" x 3" x 3" square plate.

99



100




101




102



103



104




105



106



107



108



109



110



111

Wall Sheathing

Garland, Texas – 2015



112

Wall Sheathing

Texas Straight Line Wind - 2017




113

Wall Sheathing

Texas Straight Line Wind - 2017



114



115




116



117

Larger Washer Increases Uplift Capacity

Large plate washers (3"x3"x0.229") prevent cross-grain splitting of sill plate




APA

118

Larger Washer Increases Uplift Capacity

Large plate washers (3"x3"x0.229") prevent cross-grain splitting of sill plate




APA

119

Wall Framing to Sill Plate Connection

Extend wood structural panel sheathing at bottom of wall to sill plate intersection




Other connections are not shown for clarity

APA

120

Lateral Forces

Effects of Forces



APA

121

Overturning



122


Building for High Wind Resistance



APA


123

High Wind Resistance Guidelines




124

High Wind Resistance Guidelines




125

High Wind Resistance Guidelines




126

High Wind Resistance Guidelines




127

High Wind Resistance Guidelines




128

High Wind Resistance Guidelines




129

High Wind Resistance Guidelines




130

High Wind Resistance Guidelines




131

High Wind Resistance Guidelines



132

Conclusions



133

www.apawood.org/wind-weather-seismic



134

Questions?



135

APA Update Newsletter (www.apawood.org)



Upcoming Webinar

After the Storm: Planning for High Wind Resistance

March 26 - 11:30 a.m. EST, 8:30 a.m. PST

Join APA's Regional Consultants Mike, Dave and John for a webinar focusing on common structural failure scenarios during storm damage assessments. The presentation will include an overview of high wind forces, the importance of an accurate load path, and how good design and construction practices can improve the chance of survival of a building.

Many will also discuss code requirements and present APA's alternative recommendations for wind-resistant building, as well as first attention to connection details, understanding lateral load transfer, and integrating common design practices to form damage-resistant-perhaps sufficient and effective! Build a better home and reduce future storm damage. It's 100% 100% ready and available upon completion of the webinar.

Many (over 100) of a team of APA engineers who have conducted recent storm damage assessments are providing design recommendations for your resistance.

[REGISTER NOW](#)

Updated ANSI Standard


ANSI Standard 1000-2019: Standard for Performance-Rated Cross-Laminated Timber

ANSI Standard 1000-2019: Standard for Performance-Rated Cross-Laminated Timber (CLT) is now available. The major change is ANSI/APA P308-2019 is the addition of 2017 without qualification requirements, setting full code compliance the standard in the standard based on a new fire rated standard developed by the ANSI P308-2019 Committee and published in a mandatory annex of the standard.




136

APA Update Newsletter (www.apawood.org)



137

APA Update Newsletter (www.apawood.org)



138



139
